

## Hinsdale Central School Lead Test

NYS Lab ID 11021				Method of Analysis: ASTM D3559-08D				
Lab ID #	School Sample ID	Collection date	Sample Location	Outlet Description	Initial/Post Remediation	Lead result ugl (ppb)	Lab Report Receipt date	Action taken
7070713	165-1	9/28/2020	B1 Maintenance Sink	Faucet	Initial	15.4 ppb	10/1/2020	Retest
7070714	165-2	9/28/2020	B1 Kitchen Sink	Faucet	Initial	3.60 ppb	10/1/2020	N/A
7070715	165-3	9/28/2020	B3 Kitchen By Dishwasher	Faucet	Initial	2.2 ppb	10/1/2020	N/A
7070716	165-3A	9/28/2020	B3 Dishwasher spray	Sprayer	Initial	1.9 ppb	10/1/2020	N/A
7070717	165-4B	9/28/2020	Basement water fountain	Fountain	Initial	<1.00 ppb	10/1/2020	N/A
7070718	165-5	9/28/2020	Men's Sink Closest to door	Faucet	Initial	7.90 ppb	10/1/2020	N/A
7070719	165-6	9/28/2020	Men's sink furthest from door	Faucet	Initial	5.3 ppb	10/1/2020	N/A
7070720	165-7	9/28/2020	Women's sink closest to door	Faucet	Initial	<1.0 ppb	10/1/2020	N/A
7070721	165-8	9/28/2020	Women's sink furthest from door	Faucet	Initial	1.10 ppb	10/1/2020	N/A
7070722	165-9	9/28/2020	Cafeteria Bathroom sink	Faucet	Initial	3.20 ppb	10/1/2020	N/A
7070723	165-10	9/28/2020	Elementary Library	Faucet	Initial	1.50 ppb	10/1/2020	N/A
7070724	165-11	9/28/2020	District Office	Faucet	Initial	1.60 ppb	10/1/2020	N/A
7070725	165-12	9/28/2020	RM 4	Faucet	Initial	6.20 ppb	10/1/2020	N/A
7070726	165-13B	9/28/2020	DF Next to Rm 4	Fountain	Initial	<1.0 ppb	10/1/2020	N/A
7070727	165-15	9/28/2020	RM 3	Faucet	Initial	3.20 ppb	10/1/2020	N/A
7070728	165-16	9/28/2020	RM 6	Faucet	Initial	1.50 ppb	10/1/2020	N/A
7070729	165-17	9/28/2020	RM 5	Faucet	Initial	3.20 ppb	10/1/2020	N/A
7070730	165-18	9/28/2020	Nurse Sink in Corner Rm	Faucet	Initial	<1.00 ppb	10/1/2020	N/A
7070731	165-19	9/28/2020	Nurse Sink Inside Door	Faucet	Initial	<1.00 ppb	10/1/2020	N/A
7070732	165-20	9/28/2020	Nurse Office Bathroom	Faucet	Initial	<1.00 ppb	10/1/2020	N/A
7070733	165-21	9/28/2020	Boys Bath by Door	Faucet	Initial	1.10 ppb	10/1/2020	N/A
7070734	165-22	9/28/2020	Boys Bath far From Door	Faucet	Initial	1.40 ppb	10/1/2020	N/A
7070735	165-23B	9/28/2020	DF By Boys Bathroom	Fountain	Initial	2.50 ppb	10/1/2020	N/A
7070736	165-25	9/28/2020	Principals Sink	Faucet	Initial	3.50 ppb	10/1/2020	N/A
7070737	165-26	9/28/2020	Girls Bath By Door	Faucet	Initial	2.70 ppb	10/1/2020	N/A
7070738	165-27	9/28/2020	Girls Bath far From Door	Faucet	Initial	1.40 ppb	10/1/2020	N/A
7070739	165-28	9/28/2020	Women's Faculty Bath	Faucet	Initial	1.80 ppb	10/1/2020	N/A

## Hinsdale Central School Lead Test

Lab Elap Id#		NYS Lab ID 11021		Method of Analysis:		ASTM D3559-08D		
Lab ID #	School Sample ID	Collection date	Sample Location	Outlet Description	Initial/Post Remediation	Lead result ugl (ppb)	Lab Report Receipt date	Action taken
7070740	165-29	9/28/2020	Men's Faculty Bath	Faucet	Initial	7.60 ppb	10/1/2020	N/A
7070741	165-30	9/28/2020	RM 22 Sink	Faucet	Initial	6.70 ppb	10/1/2020	N/A
7070742	165-31	9/28/2020	RM 22 Bath Sink	Faucet	Initial	17.0 ppb	10/1/2020	Retest
7070743	165-32	9/28/2020	RM 23 Sink	Faucet	Initial	9.0 ppb	10/1/2020	N/A
7070744	165-33	9/28/2020	RM 24 Sink	Faucet	Initial	3.80 ppb	10/1/2020	N/A
7070745	165-34	9/28/2020	RM 25 Sink	Faucet	Initial	3.50 ppb	10/1/2020	N/A
7070746	165-35	9/28/2020	RM 30 Sink	Faucet	Initial	29.5 ppb	10/1/2020	Retest
7070747	165-36B	9/28/2020	Gym DF	Fountain	Initial	2.20 ppb	10/1/2020	N/A
7070748	165-37	9/28/2020	Gym Lobby Mens by Door	Faucet	Initial	1.30 ppb	10/1/2020	N/A
7070749	165-38	9/28/2020	Gym Lobby Mens Middle	Faucet	Initial	2.30 ppb	10/1/2020	N/A
7070750	165-39	9/28/2020	Gym Lobby Men's far from door	Faucet	Initial	1.10 ppb	10/1/2020	N/A
7070751	165-40	9/28/2020	Gym Lobby Women's by door	Faucet	Initial	7.20 ppb	10/1/2020	N/A
7070752	165-41	9/28/2020	Gym Lobby Women's Middle	Faucet	Initial	2.30 ppb	10/1/2020	N/A
7070753	165-42	9/28/2020	Gym Lobby women's far from Door	Faucet	Initial	2.50 ppb	10/1/2020	N/A
7070754	165-43	9/28/2020	Girls locker Coach's Bath	Faucet	Initial	9.30 ppb	10/1/2020	N/A
7070755	165-44	9/28/2020	Girls locker sink	Faucet	Initial	3.20 ppb	10/1/2020	N/A
7070756	165-46	9/28/2020	Girls lock DF far from door	Fountain	Initial	4.60 ppb	10/1/2020	N/A
7070757	165-48	9/28/2020	Boys Locker Sink	Faucet	Initial	1.00 ppb	10/1/2020	N/A
7070758	165-49	9/28/2020	Boys Locker Coach's Bath	Faucet	Initial	87.4 ppb	10/1/2020	Retest
7070759	165-50	9/28/2020	Sr End Boys Bath by Door	Faucet	Initial	2.50 ppb	10/1/2020	N/A
7070760	165-51	9/28/2020	Sr. End Boys Bath far from Door	Faucet	Initial	2.70 ppb	10/1/2020	N/A
7070761	165-52B	9/28/2020	Sr. End DF By Boys Bath	Fountain	Initial	<1.00 ppb	10/1/2020	N/A
7070762	165-54	9/28/2020	Sr. End Girls Bath By Door	Faucet	Initial	3.20 ppb	10/1/2020	N/A
7070763	165-55	9/28/2020	Sr. End Girls Bath Far From Door	Faucet	Initial	2.20 ppb	10/1/2020	N/A
7070764	165-56	9/28/2020	Jr. End Boys Bath by Door	Faucet	Initial	2.00 ppb	10/1/2020	N/A
7070765	165-57	9/28/2020	Jr. End Boys Bath Far from Door	Faucet	Initial	2.90 ppb	10/1/2020	N/A
7070766	165-58B	9/28/2020	Jr. End DF By Boys Bath	Fountain	Initial	<1.00 ppb	10/1/2020	N/A

## Hinsdale Central School Lead Test

Lab Elap Id#		NYS Lab ID 11021		Method of Analysis:		ASTM D3559-08D		
Lab ID #	School Sample ID	Collection date	Sample Location	Outlet Description	Initial/Post Remediation	Lead result ugl (ppb)	Lab Report Receipt date	Action taken
7070767	165-60	9/28/2020	Jr. end Girls Bath Close by Door	Faucet	Initial	2.20 ppb	10/1/2020	N/A
7070768	165-61	9/28/2020	Jr. End Girls Bath Far From Door	Faucet	Initial	1.70 ppb	10/1/2020	N/A
7070769	165-62	9/28/2020	Home EC by Door	Faucet	Initial	3.00 ppb	10/1/2020	N/A
7070770	165-63	9/28/2020	Home EC Middle	Faucet	Initial	7.30 ppb	10/1/2020	N/A
7070771	165-64	9/28/2020	Home EC Far From Door	Faucet	Initial	8.00 ppb	10/1/2020	N/A
7070772	165-65B	9/28/2020	DF Outside Rm 72	Fountain	Initial	<1.00 ppb	10/1/2020	N/A
7070773	165-66	9/28/2020	Rm 78 By Door	Faucet	Initial	5.80 ppb	10/1/2020	N/A
7070774	165-67	9/28/2020	Rm 78 Far From Door	Faucet	Initial	8.50 ppb	10/1/2020	N/A
7070775	165-70	9/28/2020	5-6 Wing Boys Bath By Door	Faucet	Initial	1.90 ppb	10/1/2020	N/A
7070776	165-71	9/28/2020	5-6 Wing Boys Bath Far From Door	Faucet	Initial	1.10 ppb	10/1/2020	N/A
7070777	165-72	9/28/2020	5-6 Wing Girls Bath By Door	Faucet	Initial	1.00 ppb	10/1/2020	N/A
7070778	165-73	9/28/2020	5-6 Wing Girls Bath From from Door	Faucet	Initial	1.10 ppb	10/1/2020	N/A
7070779	165-78	9/28/2020	Rm 22 Bubbler	Fountain	Initial	6.10 ppb	10/1/2020	N/A
7070780	165-79B	9/28/2020	Gym Lobby DF	Fountain	Initial	<1.00 ppb	10/1/2020	N/A

## Hinsdale Central School Lead Test

Lab Elap Id#		NYS Lab ID 11714		Method of Analysis:		SM 3113B-2010		
Lab ID #	School Sample ID	Collection date	Sample Location	Outlet Description	Initial/Post Remediation	Lead result ugl (ppb)	Lab Report Receipt date	Action taken
21-01-01384-001	165.2-1	1/6/2021	Bus Garage Water Fountain	Fountain	Initial	<1.00 ppb	1/19/2021	N/A
21-01-01384-002	165.2-2	1/6/2021	Bus Garage Womens Bathroom	Faucet	Initial	<1.00 ppb	1/19/2021	N/A
21-01-01384-003	165.2-2	1/6/2021	Bus Garage Mens Bathroom	Faucet	Initial	<1.00 ppb	1/19/2021	N/A

## Hinsdale Central School Lead Test

Lab Elap Id#		NYS Lab ID 11714		Method of Analysis:		SM 3113B-2010		
Lab ID #	School Sample ID	Collection date	Sample Location	Outlet Description	Initial/Post Remediation	Lead result ugl (ppb)	Lab Report Receipt date	Action taken
21-01-01389-001	165.1-1	1/6/2021	B1 Maintenance Sink	Faucet	Post	<1.00 ppg	1/19/2021	N/A
21-01-01389-002	165.1-31	1/6/2021	RM 22 Bath Sink	Faucet	Post	<1.00 ppg	1/19/2021	N/A
21-01-01389-003	165.1-35	1/6/2021	RM 30 Sink	Faucet	Post	3.07 ppg	1/19/2021	N/A
21-01-01389-004	165.1-49	1/6/2021	Boys Locker Coach's Bath	Faucet	Post	<1.00 ppg	1/19/2021	N/A